MARION COUNTY SURVEYOR'S OFFICE

SECTION CORNER RECORD

DEBRA S. JENKINS BRYAN F. CATLIN, PLS SEC. 35 TWN. 15_{N} RNG. 3_{E} MARION COUNTY SURVEYOR TECHNICAL SUPERVISOR Date: 8-11-09 Party Chief: Wilcoxen \gtrsim Crew: Finney Meridian 0 Type of Marker: Harrison with IDOT cap Method of Establishment: County: See History IN S.P.C. E Zone, NAD 83 Name: 15033508 N: 493 546.443 0(m) 57 023.809 0(m) 370 Thompson Thompson 5000 S 1. 374 Thompson 5. 112.97

Original post set 1820 by Laughlin with witnesses: 14" beech N 82 E 18 links, 13" ash S 49 W 22 links per Marion County Atlas pg 6. Hosbrook, no date, called stone per Perry Township Legal Survey Book pg. 15. Tie card, no date, called pipe over stone. Another old tie card called a brass plug flush with pavement. 5-29-75 Miller called a RR spike over stone. 6-24-87 Wilcoxen excavated and found a RR spike at surface, and a stone with lead pipe beside it 6" down. Harrison set in position. Retied 6-24-1996 by Whiteside. Retied 10-01-2004 by Wilcoxen. Retied 8-11-09 by Wilcoxen.

Thompson 5000 S

Section Line

85.54'

REF.	DISTANCE	DESCRIPTION
1.	126.63'	SW corner of brick 370 Thompson
2.	26.74'	Survey mark nail N 12" hackberry 18" up
3.	85.54'	Due W to North quarter 2-14-3 (Harrison w/IDOT cap)
4.	112.97'	Top and center of steel fence post
5.	112.54'	SE corner of brick 374 Thompson